

HARDWARE LIST:

Z-318 (4) -5/16" X 1 1/4" BOLT Z-207 (4) -5/16" NUT Z-510 (4) -5/16" LOCKWASHER





INSTRUCTIONS FOR PROPER SPLICING:

BUTT TRACK SECTIONS AGAINST EACH OTHER TIGHTLY. CENTER ONE HALF OF THE SPLICE CLAMP OVER THE JOINT. MARK LOCATION OF HOLES.

DRILL (4) %" DIAMETER HOLES. COMPLETE SPLICE WITH (4) $\%_6$ " DIAMETER HEX HEAD BOLTS AND HEX NUTS.

TIGHTEN SECURELY.

2121 S. 12TH ST. ALLENTOWN, PA 18103 AUTOMATIC DEVICES COMPANY

THIS DRAWING HAS BEEN PREPARED AS A SERVICE TO OUR CUSTOMER AND IS INITENDED ONLY TO BE SUGGESTIVE IN NATURE AND IS NOT TO BE USED AS AN ACTUAL INSTALLATION DRAWING. PREVAILING JOB CONDITIONS AND ACCEPTED PRACTICES MUST BE TAKEN INTO ACCOUNT WHEN THE EQUIPMENT IS INSTALLED.

	DRAWN BY APPROVED BY DESCRIPTION	A 06/07/93	SIZE DATE	
4004 SPIICING CLAMP	BY DESCRIPTION	3 FORM 411	REV	

SCALE 1/2"=1" SHEET 1 OF 1

DWG NO. A-4224-93